


2016 Macan Turbo

VIN WP1AF2A59GLXXXXXX

Model code 95B-AF1

|                                                  |                                                   |                                     |                     |                                              |                                 |
|--------------------------------------------------|---------------------------------------------------|-------------------------------------|---------------------|----------------------------------------------|---------------------------------|
| <b>6</b><br>Dealer visits<br>Feb 2016 – Jun 2026 | <b>76,742 mi</b><br>Last recorded<br>May 26, 2026 | <b>7,406 mi</b><br>Average per year | <b>2</b><br>Dealers | <b>3</b><br>Repairs<br>1 covered by warranty | <b>6</b><br>Campaigns / recalls |
|--------------------------------------------------|---------------------------------------------------|-------------------------------------|---------------------|----------------------------------------------|---------------------------------|

Odometer history



Warranty coverage

| COVERAGE                                                                        | VALID                       | LIMIT                  | STATUS  |
|---------------------------------------------------------------------------------|-----------------------------|------------------------|---------|
| <b>New vehicle</b>                                                              | Oct 27, 2015 – Oct 27, 2019 | 50,000 mi / 81,000 km  | Expired |
| <b>New vehicle</b><br>Extended warranty for transfer box                        | Oct 27, 2015 – Oct 27, 2022 | Unlimited              | Expired |
| <b>New vehicle</b><br>Transmission electronics control unit - programming error | Oct 27, 2015 – Oct 27, 2035 | Unlimited              | Active  |
| <b>New vehicle</b><br>Extended warranty for speed sensor                        | Oct 28, 2019 – Oct 27, 2025 | Unlimited              | Expired |
| <b>Corrosion</b>                                                                | Oct 27, 2019 – Oct 27, 2027 | Unlimited              | Active  |
| <b>Emission</b><br>CARB emission guarantee                                      | Oct 27, 2019 – Oct 27, 2022 | 69,000 mi / 112,000 km | Expired |

## Service visits oldest first

### VISIT 1

Feb 2, 2016

#### Momentum Porsche

Dealer 450-066-4

378 mi (608 km)

##### CAMPAIGN

Replacing fuel low-pressure line in the engine compartment · Campaign AF061 **Warranty**

##### CAMPAIGN

Re-program all-wheel drive control unit · Campaign WF801 **Warranty**

### VISIT 2

Mar 27, 2017

#### Momentum Porsche

Dealer 450-066-4

2,814 mi (4,529 km)

##### CAMPAIGN

Check pressure compensation element on control unit for power-steering gear and replace it if necessary · Campaign WF881 **Warranty**

### VISIT 3

Nov 9, 2017

#### Porsche North Houston

Dealer 450-075-1 · Repair order #063154

3,781 mi (6,085 km)

##### CAMPAIGN

Repairs to flange of fuel filter unit · Campaign AH061 **Warranty**

### VISIT 4

Nov 21 – Dec 1, 2017

11 days at dealer

#### Porsche North Houston

Dealer 450-075-1 · Repair order #063441

3,910 mi (6,293 km)

##### Vehicle arrived as a breakdown

##### VISIT

Serial number update

new transmission serial number. 006pfad026382k1704283

##### REPAIR

Double-clutch transmission · Leaks **Warranty**

### VISIT 5

Oct 9 – Oct 11, 2019

3 days at dealer

#### Porsche North Houston

Dealer 450-075-1 · Repair order #86533

9,545 mi (15,361 km)

##### VISIT

General workshop visit / Service

*Booked online*

CUSTOMER REQUESTED A LOANER TAKEN BY

VISIT 6

May 26 – Jun 5,  
2026

11 days at dealer

Porsche North Houston

Dealer 450-075-1 · Repair order #267099

76,742 mi (123,504 km)

|          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|----------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| CAMPAIGN | Reworking or replacing service cover for fuel pump · Campaign ALA28                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| REPAIR   | Seat occupancy detection control unit · Programming error                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| REPAIR   | Seat occupancy detection · No function                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
| CAMPAIGN | Replace seat occupancy detection system for passenger side · Campaign AMA2G                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| VISIT    | <div>Other</div> <div>While performing AMA2 Replace seat occupancy detection system for passenger side, the new seat mat would not program.While performing AMA2 Replace seat occupancy detection system for passenger side, the new seat mat would not program the second time. While performing AMA2 Replace seat occupancy detection system for passenger side, the new seat mat would not program the second time. The control unit cannot be programmed. Replaced the seat mat and control unit set.</div> |

Service records are reported by authorized Porsche dealers and workshops and are shown as received; technician notes appear in their original language. While we strive for accuracy, VIN Analytics is not responsible for errors or omissions in this report or for results obtained from its use. Please verify details with an authorized Porsche dealer or Porsche Customer Service. We disclaim all warranties, including implied warranties of merchantability or fitness for a particular purpose. All trademarks, trade names, service marks, product names, option names and logos are the property of their respective owners.

