


2016 Macan Turbo

VIN WP1AF2A59GLXXXXXX

Model code 95B-AF1

6 Dealer visits Feb 2016 – Jun 2026	76,742 mi Last recorded May 26, 2026	7,406 mi Average per year	2 Dealers	3 Repairs 1 covered by warranty	6 Campaigns / recalls
--	---	-------------------------------------	---------------------	--	---------------------------------

Odometer history



Warranty coverage

COVERAGE	VALID	LIMIT	STATUS
New vehicle	Oct 27, 2015 – Oct 27, 2019	50,000 mi / 81,000 km	Expired
New vehicle Extended warranty for transfer box	Oct 27, 2015 – Oct 27, 2022	Unlimited	Expired
New vehicle Transmission electronics control unit - programming error	Oct 27, 2015 – Oct 27, 2035	Unlimited	Active
New vehicle Extended warranty for speed sensor	Oct 28, 2019 – Oct 27, 2025	Unlimited	Expired
Corrosion	Oct 27, 2019 – Oct 27, 2027	Unlimited	Active
Emission CARB emission guarantee	Oct 27, 2019 – Oct 27, 2022	69,000 mi / 112,000 km	Expired

Service visits oldest first

VISIT 1

Feb 2, 2016

Momentum Porsche

Dealer 450-066-4

378 mi (608 km)

CAMPAIGN

Replacing fuel low-pressure line in the engine compartment · Campaign AF061 **Warranty**

CAMPAIGN

Re-program all-wheel drive control unit · Campaign WF801 **Warranty**

VISIT 2

Mar 27, 2017

Momentum Porsche

Dealer 450-066-4

2,814 mi (4,529 km)

CAMPAIGN

Check pressure compensation element on control unit for power-steering gear and replace it if necessary · Campaign WF881 **Warranty**

VISIT 3

Nov 9, 2017

Porsche North Houston

Dealer 450-075-1 · Repair order #063154

3,781 mi (6,085 km)

CAMPAIGN

Repairs to flange of fuel filter unit · Campaign AH061 **Warranty**

VISIT 4

Nov 21 – Dec 1, 2017

11 days at dealer

Porsche North Houston

Dealer 450-075-1 · Repair order #063441

3,910 mi (6,293 km)

Vehicle arrived as a breakdown

VISIT

Serial number update

new transmission serial number. 006pfad026382k1704283

REPAIR

Double-clutch transmission · Leaks **Warranty**

VISIT 5

Oct 9 – Oct 11, 2019

3 days at dealer

Porsche North Houston

Dealer 450-075-1 · Repair order #86533

9,545 mi (15,361 km)

VISIT

General workshop visit / Service

Booked online

CUSTOMER REQUESTED A LOANER TAKEN BY

VISIT 6
May 26 – Jun 5,
2026
11 days at dealer

Porsche North Houston
Dealer 450-075-1 · Repair order #267099
76,742 mi (123,504 km)

CAMPAIGN	Reworking or replacing service cover for fuel pump · Campaign ALA28
REPAIR	Seat occupancy detection control unit · Programming error
REPAIR	Seat occupancy detection · No function
CAMPAIGN	Replace seat occupancy detection system for passenger side · Campaign AMA2G
VISIT	Other While performing AMA2 Replace seat occupancy detection system for passenger side, the new seat mat would not program.While performing AMA2 Replace seat occupancy detection system for passenger side, the new seat mat would not program the second time. While performing AMA2 Replace seat occupancy detection system for passenger side, the new seat mat would not program the second time. The control unit cannot be programmed. Replaced the seat mat and control unit set.

Service records are reported by authorized Porsche dealers and workshops and are shown as received; technician notes appear in their original language. While we strive for accuracy, VIN Analytics is not responsible for errors or omissions in this report or for results obtained from its use. Please verify details with an authorized Porsche dealer or Porsche Customer Service. We disclaim all warranties, including implied warranties of merchantability or fitness for a particular purpose. All trademarks, trade names, service marks, product names, option names and logos are the property of their respective owners.



© 2026 VIN Analytics, LLC. All rights reserved. · vinanalytics.com