



Dealer Service History

VIN: 5UXKS4C57F0XXXXXX

2015 X5 xDrive35d (F15 / KS43)

Total Service Jobs: 18

Latest Key Reading

BMW of Alexandria , Alexandria

As of Date: September 27, 2024

Odometer Value: 64,813 mi (104,306 km)

Item Status

Item	Status	Due on	Distance
Brake fluid	Due soon	09/2024	
Engine oil	Not due	10/2024	3400
Re-circulated air filter	Not due		
Microfilter	Not due		
Fuel filter	Not due		
Statutory vehicle inspection	Not due	10/2024	
Statutory emissions test	Not due	10/2024	
Rear brakes	Not due		5000
Front Brake	Not due		18000
Vehicle check	Not due	10/2027	46000
Air filter element	Not due	10/2024	3400

Service Jobs

Service Job #1 - BMW of Alexandria , Alexandria

Service Dates: September 27, 2024 - September 30, 2024
Odometer Value: 64,839 mi (104,349 km)

Services Performed

Symptom	Action	Parts
Engine Oil Service (OEM)	OIL SERVICE	-BMW TwinPower Turbo LL-04 5W-30 -Set oil-filter element -Diesel exhaust fluid AdBlue
CUSTOMER PAY STATE INSPECTION	CUSTOMER PAY STATE INSPECTION	
BG Perform Brake Flush Dealer Recommended	BG Perform Brake Flush Dealer Recommended	-BMW Non-Chlor. Brake Parts Cleaner 45% -BG BRAKE FLUID DOT 4 KIT
Windshield Wiper Blade - Front - Replace	Windshield Wiper Blade - Front - Replace	-Set of wiper blades
ROTATE ALL 4 TIRES WITHOUT BALANCE	ROTATE ALL 4 TIRES WITHOUT BALANCE	
Air Filter Cartridge - Replace	Air Filter Cartridge - Replace	-Air filter element
PERFORM MULTI POINT INSPECTION/VIDEO	PERFORM MULTI POINT INSPECTION/VIDEO	

Service Job #2 - BMW of Alexandria , Alexandria

Service Dates: December 28, 2023 - January 11, 2024
Odometer Value: 59,811 mi (96,257 km)

Services Performed

Symptom	Action	Parts
replace the aux egr cooler at the particulate filter	replace the aux egr cooler at the particulate filter	-exhaust cooler -Gasket Steel -Gasket Steel -Screw -Hex nut -ASA-Bolt
CUSTOMER STATES Check engine light with error code P241F	TESTING FOR SPECIFIC CUSTOMER CONCERN	

related to EGR.		
PERFORM MULTI POINT INSPECTION/VIDEO	PERFORM MULTI POINT INSPECTION/VIDEO	

Service Job #3 - BMW of Alexandria , Alexandria

Service Dates: October 11, 2023 - October 16, 2023

Odometer Value: 58,431 mi (94,035 km)

Services Performed

Symptom	Action	Parts
Engine Oil Service (OEM)	Engine Oil Service (OEM)	-BMW TwinPower Turbo LL-04 5W-30 -Set oil-filter element -Diesel exhaust fluid AdBlue
SCHEDULED MAINTENANCE VEHICLE CHECK	SCHEDULED MAINTENANCE VEHICLE CHECK	
Fuel Filter - Replace	Fuel Filter - Replace	-Hose clamp -Fuel filter cartridge
Microfilter - Replace (OEM)	Microfilter - Replace (OEM)	-BG FRIGI-FRESH 24/1OZ -Set, microfilter/activ. charcoal filter -Microfilter, recirculated air
Filter, Air Recirculating - Replace	Filter, Air Recirculating - Replace	-Air filter element
CUSTOMER STATES CHECK ENGINE AND DRIVETRAIN MALFUNCTION LIGHT ON. CHECK AND ADVISE	Carrying out vehicle test	-Exhaust gas cooler low temperature -AGR small parts set -Pipe union -Holder -O-ring -Antifreeze
found faulty fuel injector 5 causing misfire and EGR faults replace 1 injector then check	Fuel Injectors - Replace	-Injector
Align Suspension - Front and Rear	Align Suspension - Front and Rear	
Mounts, Front Thrust Strut dry rod torn clunking effecting front tires - Replace (OEM)	Mounts, Front Thrust Strut dry rod torn clunking effecting front tires - Replace (OEM)	-Rubber Mounting -Hexagon screw with flange -Self-locking collar nut -Combination nut -Collar nut
PERFORM MULTI POINT	PERFORM MULTI POINT	

INSPECTION/VIDEO	INSPECTION/VIDEO	
PROVIDED LOANER FOR CUSTOMER	PROVIDED LOANER FOR CUSTOMER	

Service Job #4 - BMW of Alexandria , Alexandria

Service Dates: February 22, 2023 - February 22, 2023

Odometer Value: 54,544 mi (87,780 km)

Services Performed

Symptom	Action	Parts
CAMPAIGNS/RECALLS B 111021	Replacing exhaust gas recirculation cooler including exhaust gas recirculation valve Performing additional work for pressure sensor functional check Additional work: enter component identification of new exhaust-gas recirculation cooler in diagnostic system Additional work: clean exhaust-gas recirculation pipe (do not use when replacing intake system) Additional work: Replace coolant hose on exhaust-gas recirculation cooler incl. temperature sensor Additional work: replace exhaust-gas recirculation cooler line to coolant pump	-Acoustic cover front -Exhaust gas cooler low temperature -Coolant hose -Line EGR radiator-coolant pump -Holder -O-ring -Pipe union -AGR small parts set
PERFORM MULTI POINT INSPECTION/VIDEO	PERFORM MULTI POINT INSPECTION/VIDEO	
PROVIDED LOANER FOR CUSTOMER	PROVIDED LOANER FOR CUSTOMER	

Service Job #5 - BMW of Alexandria , Alexandria

Service Dates: September 14, 2022 - September 14, 2022

Odometer Value: 53,662 mi (86,360 km)

Services Performed

Symptom	Action	Parts
CLIENT STATES THAT HE WOULD LIKE TO REMOVE THE WHEEL LOCKS AND REPLACE LOCKS WITH LUG NUTS. CHECK AND ADVISE	INFORMATION LINE ONLY	

CLIENT REQUEST A PRICE ON THE FRONT BRAKE SERVICE	CLIENT REQUEST A PRICE ON THE FRONT BRAKE SERVICE	
Pads and Rotors, Brake (Front) - Replace (OEM)	Pads and Rotors, Brake (Front) - Replace (OEM)	-Torx-bolt with washer -Repair kit, brake pads asbestos-free -Brake disc, ventilated -Inner hex bolt -Brake pad wear sensor, front left -Brake pad paste -BMW Non-Chlor. Brake Parts Cleaner 45%
CUSTOMER PAY STATE INSPECTION	CUSTOMER PAY STATE INSPECTION	
WHEEL LOCK REMOVAL AND INSTALL 4 REGULAR LUG BOLTS (PLEASE PRICE BOLTS)	Miscellaneous Wheel/Tires - Repair	-Wheel bolt black
BG FINAL FRONT DRIVE UNIT PERFORM DEALER RECOMMENDED	BG FINAL FRONT DRIVE UNIT PERFORM DEALER RECOMMENDED	-ULTRA GUARD -BMW Non-Chlor. Brake Parts Cleaner 45% -Screw plug with O-ring
BG REAR FINAL DRIVE SERVICE DEALER RECOMMENDED	BG REAR FINAL DRIVE SERVICE DEALER RECOMMENDED	-ULTRA GUARD -BMW Non-Chlor. Brake Parts Cleaner 45% -Screw plug with O-ring
BG TRANSFER CASE SERVICE PERFORM DEALER	BG TRANSFER CASE SERVICE PERFORM DEALER	-BG SYNCRO SHIFT2 -Screw plug with O-ring -BMW Non-Chlor. Brake Parts Cleaner 45%
B111021 RECALL: EXHAUST GAS RECIRCULATION COOLER - N57T LOW TEMPERATURE	PART HAS BEEN SPECIAL ORDERED. CUSTOMER WILL BE CONTACTED.	
PERFORM MULTIPOINT INSPECTION/VIDEO	PERFORM MULTIPOINT INSPECTION/VIDEO	
CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	

Service Job #6 - BMW of Alexandria , Alexandria

Service Dates: March 5, 2021 - March 5, 2021
Odometer Value: 52,239 mi (84,071 km)

Services Performed

Symptom	Action	Parts
customer returning to have both vehicle batteries replaced	customer returning to have both vehicle batteries replaced	-Original BMW AGM-battery

		-EP Battery 92AH
CUSTOMER DECLINES MULTI POINT INSPECTION	CUSTOMER DECLINES MULTI POINT INSPECTION	
CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	

Service Job #7 - BMW of Alexandria , Alexandria

Service Dates: January 28, 2021 - January 29, 2021

Odometer Value: 52,977 mi (85,258 km)

Services Performed

Symptom	Action	Parts
CUSTOMER WAS TOLD ON PREVIOUS SERVICE BOTH BATTERIES SHOULD BE REPLACED, PLEASE CHECK	NO WORK PERFORMED	
PERFORM MULTI POINT INSPECTION	NO WORK PERFORMED	
CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	NO WORK PERFORMED	

Service Job #8 - BMW of Alexandria , Alexandria

Service Dates: August 17, 2020 - August 17, 2020

Odometer Value: 51,828 mi (83,409 km)

Services Performed

Symptom	Action	Parts
CUSTOMER STATES CHECK ENGINE LIGHT IS ON SINCE LAST SERVICE	Carrying out vehicle test Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Verifying customer concern and diagnosing cause Replacing diesel particulate sensor	-diesel particulate sensor
PERFORM MULTIPOINT INSPECTION	PERFORM MULTIPOINT INSPECTION	
CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	

Service Job #9 - BMW of Alexandria , Alexandria

Service Dates: August 10, 2020 - August 10, 2020

Odometer Value: 51,755 mi (83,292 km)

Services Performed

Symptom	Action	Parts
Air Filter Cartridge - Replace	Air Filter Cartridge - Replace	-Air filter element
Condition Based Service - Microfilter	Condition Based Service - Microfilter	-BG FRIGI-FRESH 24/10Z -Set, microfilter/activ. charcoal filter
CUSTOMER PAY STATE INSPECTION	CUSTOMER PAY STATE INSPECTION	
Condition Based Service - Microfilter	Condition Based Service - Microfilter	-Microfilter, recirculated air
Engine Oil Service (OEM)	Engine Oil Service (OEM)	-BMW TwinPower Turbo LL-04 5W-30 -Set oil-filter element -Diesel exhaust fluid AdBlue
4 CYLINDER OIL CHANGE SPECIAL	Engine oil service	
CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	CUSTOMER IS WAITING ON VEHICLE TO BE REPAIRED	

Service Job #10 - BMW of Alexandria , Alexandria

Service Dates: November 11, 2019 - November 14, 2019

Odometer Value: 49,623 mi (79,861 km)

Services Performed

Symptom	Action	Parts
Passenger front tire has a nail Goodyear EAGLE LS2 ROF (BMW) XL BW	Passenger front tire has a nail Goodyear EAGLE LS2 ROF (BMW) XL BW	-Goodyear eagle ls2
Mounts, Front Thrust Strut - Replace (OEM)	Mounts, Front Thrust Strut - Replace (OEM)	-Rubber Mounting -Combination nut -Self-locking collar nut
FRONT WISHBONE ON PASSENGER SIDE CAUSING KNOCKING NOISE. RECOMMEND	FRONT WISHBONE ON PASSENGER SIDE CAUSING KNOCKING NOISE. RECOMMEND	-Wishbone, bottom,with rubber mount right -Wishbone, bottom, with rubber mount left

REPLACEMENT OF BOTH WISHBONES.	REPLACEMENT OF BOTH WISHBONES.	-Combination nut -Combination nut -Hexagon screw with flange -Hexagon screw with flange
Align Suspension - Front and Rear	Align Suspension - Front and Rear	
CUSTOMER STATES Getting a knocking noise from the passenger front suspension when driving at low speeds and going over bumps	CUSTOMER STATES	
Customer inquiry on getting replacement driver front floor mat	NO WORK PERFORMED	
PROVIDED LOANER FOR CUSTOMER	PROVIDED LOANER FOR CUSTOMER	

Service Job #11 - BMW of Alexandria , Alexandria

Service Dates: August 19, 2019 - August 19, 2019

Odometer Value: 47,303 mi (76,127 km)

Services Performed

Symptom	Action	Parts
CUSTOMER PAY STATE INSPECTION	CUSTOMER PAY STATE INSPECTION	
STATE EMISSION TEST	STATE EMISSION TEST	
CAMPAIGNS/RECALLS B111718	Visual inspection of the EGR cooler outlet and cooler inlet; Check the Check Control message for coolant level	
BG Perform Brake Flush Dealer Recommended	BG Perform Brake Flush Dealer Recommended	-BG BRAKE FLUID DOT 4 KIT -BMW Non-Chlor. Brake Parts Cleaner 45%
reset the system after service	reset the system after service	

Service Job #12 - BMW of Alexandria , Alexandria

Service Dates: May 2, 2019 - May 2, 2019

Odometer Value: 44,838 mi (72,159 km)

Services Performed

Symptom	Action	Parts
Engine Oil Service (OEM)	Engine Oil Service (OEM)	-BMW TwinPower Turbo LL-04 5W-30 -Set oil-filter element -Diesel exhaust fluid AdBlue
CEL IS ON NEED DIAG	CEL IS ON NEED DIAG	
PROVIDED LOANER FOR CUSTOMER	PROVIDED LOANER FOR CUSTOMER	

Service Job #13 - BMW of Alexandria , Alexandria

Service Dates: August 6, 2018 - August 9, 2018

Odometer Value: 39,425 mi (63,448 km)

Services Performed

Symptom	Action	Parts
CUSTOMER STATES THE AIR CONDITIONING WILL BE ON BUT NOT BLOWING ANY AIR. YOU CAN HEAR IT BUT NO AIR IS COMING OUT. IT SEEMS TO BE WORKING AT THIS MOMENT. IT BLOWS COLD WHEN THE AIR IS MOVING. IT WILL JUST STOPS COMING OUT OF THE FRONT VENTS.	Carrying out vehicle test Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Program/encode control unit(s), includes deleting the fault memory	
State Inspection	State Inspection	
CUSTOMER TOOK UBER BMW OF ALEXANDRIA WILL REIMBURSE UP TO \$30.00	CUSTOMER TOOK UBER BMW OF ALEXANDRIA WILL REIMBURSE UP TO \$30.00	

Service Job #14 - BMW of Alexandria , Alexandria

Service Dates: May 29, 2018 - June 1, 2018

Odometer Value: 37,326 mi (60,071 km)

Services Performed

Symptom	Action	Parts
C/S CHECK ENGINE LIGHT IS ON	Supporting the voltage of the vehicle electrical system/recharging the vehicle electrical system battery Carrying out vehicle test	-Injector

	Carrying out vehicle diagnosis, ABL Work time without specification/fuel treatment Replacing all injectors of the injection system Work time without specification/fuel supply Resume vehicle test and clear fault memory	
PROVIDED CUSTOMER WITH BMW LOANER VEHICLE (MUST PROVIDE VALID LICENSE, INSURANCE INFORMATION, AND A CREDIT CARD)	PROVIDED CUSTOMER WITH BMW LOANER VEHICLE (MUST PROVIDE VALID LICENSE, INSURANCE INFORMATION, AND A CREDIT CARD)	

Service Job #15 - BMW of Alexandria , Alexandria

Service Dates: May 14, 2018 - May 14, 2018

Odometer Value: 36,796 mi (59,217 km)

Services Performed

Symptom	Action	Parts
C/S DRIVER FRONT TIRE HAS A NAIL	MOUNT AND BALANCE 1 TIRE/WHEEL	-WEIGHTS -DISPOSAL. -Goodyear eagle ls2
CUSTOMER WAITING WHILE VEHICLE BEING REPAIRED	CUSTOMER WAITING WHILE VEHICLE BEING REPAIRED	

Service Job #16 - BMW of Alexandria , Alexandria

Service Dates: April 2, 2018 - April 9, 2018

Odometer Value: 35,460 mi (57,068 km)

Services Performed

Symptom	Action	Parts
0013550200 B130116 Service Action: Program Control Units B13 01 16	Program and code control units	
CLIENTS TATES DRIVE TRAIN MALMFUNCTION LIGHT CAME ON AND WAS TOLD THE TURBOWASTE GATE WAS BLOWN OUT AND NEEDS TURBO	Performing vehicle test	-Turbo charger -Gasket ring -Hex bolt -Hollow bolt -Gasket Asbestos Free -Hose -Screw clamp -Gasket Steel

		-Return pipe -Muffler clamp -Gasket -Hose clamp -Preformed seal -Antifreeze -Gasket ring
CLIENT STATES REAR WINDSHIELD NOZZLE WILL NOT SPRAY ON GLASS	Replacing water jet for rear window washer system	-Spray nozzle with hose
PERFORM STANDARD SCOPE SERVICE	Standard scope of service	
OIL SERVICE IS DUE PER SBC	Engine oil service	-BMW TwinPower Turbo LL-04 5W-30 -Set oil-filter element -Diesel exhaust fluid AdBlue -BMW Windshield Washer Fluid - 8 oz
FUEL FILTER IS DUE WITH OIL SERVICE PER SBC	Fuel filter service	-Hose clamp -Fuel filter cartridge
MICROFILTER IS DUE WITH OIL SERVICE PER SBC	Service - microfilter	-Set, microfilter/activ. charcoal filter -Microfilter, recirculated air
VEHICLE CHECK IS DUE PER SBC	Vehicle check service	
CHECK REAR BRAKES	NO WORK PERFORMED	
TOP OFF ALL FLUIDS AND TIRE PRESSURE	TOPPING OFF FLUIDS	
PROVIDED CUSTOMER WITH BMW LOANER VEHICLE (MUST PROVIDE VALID LICENSE, INSURANCE INFORMATION, AND A CREDIT CARD)	PROVIDED CUSTOMER WITH BMW LOANER VEHICLE (MUST PROVIDE VALID LICENSE, INSURANCE INFORMATION, AND A CREDIT CARD)	

Service Job #17 - Leith BMW Rolls-Royce Motor Cars Raleigh , Raleigh

Service Dates: March 30, 2018 - March 30, 2018
Odometer Value: 35,135 mi (56,545 km)

Services Performed

Symptom	Action	Parts
CUSTOMER STATES VEHICLE HAS A DRIVETRAIN	Performing vehicle test Supporting the voltage of the	

MALFUNCTION. CHECK AND ADVISE.	vehicle electrical system/recharging the vehicle electrical system battery Work time without specification/engine	
LEITH BMW COMPLIMENTARY MULTI-POINT VEHICLE INSPECTION	LEITH BMW COMPLIMENTARY MULTI-POINT VEHICLE INSPECTION	

Service Job #18 - BMW of Alexandria , Alexandria

Service Dates: August 25, 2017 - August 25, 2017
Odometer Value: 28,637 mi (46,086 km)

Services Performed

Symptom	Action	Parts
STANDARD SCOPE	Standard scope of service	
ENGINE OIL CHANGE	Engine oil service	-BMW TwinPower Turbo LL-04 5W-30 -Set oil-filter element -Diesel exhaust fluid AdBlue -BMW Windshield Washer Fluid - 8 oz
INTAKE SILENCE	Service - air filter insert	-Air filter element
BRAKE FLUID	Brake fluid service	-Brake fluid
CUSTOMER PAY STATE INSPECTION	CUSTOMER PAY STATE INSPECTION	
CUSTOMER EMISSIONS INSPECTION	CUSTOMER EMISSIONS INSPECTION	
FRONT WIPERS NOT CLEARING WELL	Replace left and right wiper blade	-Set of wiper rubber
REAR WIPERS NOT CLEARING WELL	Replacing the wiper blade for the rear wiper	-Wiper blade
CUSTOMER WAITING WHILE VEHICLE BEING REPAIRED	CUSTOMER WAITING WHILE VEHICLE BEING REPAIRED	

Historical Key Readings

Key Values #1 - BMW of Alexandria , Alexandria

As of Date: January 6, 2024
Odometer Value: 59,809 mi (96,253 km)

Item Status

Item	Status	Due on	Distance
Rear brakes	Not due		6000
Brake fluid	Not due	09/2024	
Engine oil	Not due	10/2024	13000
Re-circulated air filter	Not due		
Microfilter	Not due		
Fuel filter	Not due		
Statutory vehicle inspection	Not due	10/2024	
Statutory emissions test	Not due	10/2024	
Front Brake	Not due		21000
Vehicle check	Not due	10/2027	60000
Air filter element	Not due	10/2024	13000

Key Values #2 - BMW of Alexandria , Alexandria

As of Date: December 28, 2023
Odometer Value: 59,787 mi (96,218 km)

Item Status

Item	Status	Due on	Distance
Rear brakes	Not due		6000
Brake fluid	Not due	09/2024	
Engine oil	Not due	10/2024	13000
Re-circulated air filter	Not due		
Microfilter	Not due		
Fuel filter	Not due		
Statutory vehicle inspection	Not due	10/2024	
Statutory emissions test	Not due	10/2024	
Front Brake	Not due		21000
Vehicle check	Not due	10/2027	60000
Air filter element	Not due	10/2024	13000

Key Values #3 - BMW of Alexandria , Alexandria

As of Date: October 11, 2023
Odometer Value: 58,407 mi (93,997 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Overdue	09/2023	6000
Air filter element	Not due		
Statutory vehicle inspection	Overdue	09/2023	
Statutory emissions test	Overdue	09/2023	
Vehicle check	Overdue	09/2023	6000
Rear brakes	Not due		7000
Brake fluid	Not due	09/2024	
Front Brake	Not due		24000
Fuel filter	Overdue	09/2023	6000
Microfilter	Overdue	09/2023	6000
Re-circulated air filter	Overdue	09/2023	6000

Key Values #4 -

As of Date: February 22, 2023
Odometer Value: 54,504 mi (87,716 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Not due	09/2023	12000
Air filter element	Not due		
Statutory vehicle inspection	Not due	09/2023	
Statutory emissions test	Not due	09/2023	
Vehicle check	Not due	09/2023	12000
Brake fluid	Not due	09/2024	
Rear brakes	Not due		12000
Front Brake	Not due		31000
Fuel filter	Not due	09/2023	12000
Microfilter	Not due	09/2023	12000
Re-circulated air filter	Not due	09/2023	12000

Key Values #5 - BMW of Alexandria , Alexandria

As of Date: September 14, 2022
Odometer Value: 53,640 mi (86,326 km)

Item Status

Item	Status	Due on	Distance
Statutory vehicle inspection	Due soon	09/2022	
Engine oil	Not due	09/2023	14000
Air filter element	Not due		

Statutory emissions test	Not due	09/2023	
Vehicle check	Not due	09/2023	14000
Brake fluid	Not due	09/2024	
Rear brakes	Not due		15000
Front Brake	Not due		18000
Fuel filter	Not due	09/2023	14000
Microfilter	Not due	09/2023	14000
Re-circulated air filter	Not due	09/2023	14000

Key Values #6 -

As of Date: March 5, 2021
Odometer Value: 52,218 mi (84,037 km)

Item Status

Item	Status	Due on	Distance
Brake fluid	Not due	08/2021	
Engine oil	Not due	08/2021	14000
Re-circulated air filter	Not due		
Microfilter	Not due		
Air filter element	Not due		
Fuel filter	Not due		
Statutory vehicle inspection	Not due	08/2021	
Statutory emissions test	Not due	08/2021	
Vehicle check	Not due	08/2022	28000
Rear brakes	Not due		20000
Front Brake	Not due		21000

Key Values #7 - BMW of Alexandria , Alexandria

As of Date: August 17, 2020
Odometer Value: 51,807 mi (83,376 km)

Item Status

Item	Status	Due on	Distance
Brake fluid	Not due	08/2021	
Engine oil	Not due	08/2021	14000
Re-circulated air filter	Not due		
Microfilter	Not due		
Air filter element	Not due		
Fuel filter	Not due		
Statutory vehicle inspection	Not due	08/2021	
Statutory emissions test	Not due	08/2021	
Vehicle check	Not due	08/2022	28000

Rear brakes	Not due		21000
Front Brake	Not due		21000

Key Values #8 - BMW of Alexandria , Alexandria

As of Date: August 10, 2020
Odometer Value: 51,733 mi (83,257 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Overdue	05/2020	2900
Fuel filter	Not due		
Statutory vehicle inspection	Due soon	08/2020	
Brake fluid	Not due	08/2021	
Statutory emissions test	Not due	08/2021	
Vehicle check	Not due	05/2022	31000
Rear brakes	Not due		21000
Front Brake	Not due		21000
Air filter element	Overdue		2900
Microfilter	Overdue		2900
Re-circulated air filter	Overdue		2900

Key Values #9 - BMW of Alexandria , Alexandria

As of Date: November 11, 2019
Odometer Value: 49,603 mi (79,829 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Not due	05/2020	6000
Fuel filter	Not due		
Statutory vehicle inspection	Not due	08/2020	
Front Brake	Not due		23000
Rear brakes	Not due		25000
Brake fluid	Not due	08/2021	
Statutory emissions test	Not due	08/2021	
Vehicle check	Not due	05/2022	34000
Air filter element	Not due		6000
Microfilter	Not due		6000
Re-circulated air filter	Not due		6000

Key Values #10 - BMW of Alexandria , Alexandria

As of Date: August 19, 2019
Odometer Value: 47,275 mi (76,082 km)

Item Status

Item	Status	Due on	Distance
Brake fluid	Due soon	08/2019	
Statutory vehicle inspection	Due soon	08/2019	
Statutory emissions test	Due soon	08/2019	
Engine oil	Not due	05/2020	10000
Fuel filter	Not due		
Front Brake	Not due		32000
Rear brakes	Not due		33000
Vehicle check	Not due	05/2022	38000
Air filter element	Not due		10000
Microfilter	Not due		10000
Re-circulated air filter	Not due		10000

Key Values #11 - BMW of Alexandria , Alexandria

As of Date: May 2, 2019
Odometer Value: 44,795 mi (72,090 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Due soon	04/2019	140
Re-circulated air filter	Not due		
Microfilter	Not due		
Air filter element	Not due		
Fuel filter	Not due		
Brake fluid	Not due	08/2019	
Statutory vehicle inspection	Not due	08/2019	
Statutory emissions test	Not due	08/2019	
Front Brake	Not due		39000
Rear brakes	Not due		40000
Vehicle check	Not due	04/2022	46000

Key Values #12 - BMW of Alexandria , Alexandria

As of Date: August 6, 2018
Odometer Value: 39,409 mi (63,423 km)

Item Status

Item	Status	Due on	Distance
Statutory vehicle inspection	Due soon	08/2018	
Front Brake	Not due		5000
Rear brakes	Not due		5000
Engine oil	Not due	04/2019	10000
Re-circulated air filter	Not due		
Microfilter	Not due		
Air filter element	Not due		
Fuel filter	Not due		
Brake fluid	Not due	08/2019	
Statutory emissions test	Not due	08/2019	
Vehicle check	Not due	04/2022	60000

Key Values #13 - BMW of Alexandria , Alexandria

As of Date: May 29, 2018
Odometer Value: 37,311 mi (60,046 km)

Item Status

Item	Status	Due on	Distance
Rear brakes	Not due		5000
Statutory vehicle inspection	Not due	08/2018	
Front Brake	Not due		8000
Engine oil	Not due	04/2019	13000
Re-circulated air filter	Not due		
Microfilter	Not due		
Air filter element	Not due		
Fuel filter	Not due		
Brake fluid	Not due	08/2019	
Statutory emissions test	Not due	08/2019	
Vehicle check	Not due	04/2022	60000

Key Values #14 - BMW of Alexandria , Alexandria

As of Date: May 14, 2018
Odometer Value: 36,781 mi (59,193 km)

Item Status

Item	Status	Due on	Distance
Rear brakes	Not due		5000
Statutory vehicle inspection	Not due	08/2018	
Front Brake	Not due		9000
Engine oil	Not due	04/2019	14000

Re-circulated air filter	Not due		
Microfilter	Not due		
Air filter element	Not due		
Fuel filter	Not due		
Brake fluid	Not due	08/2019	
Statutory emissions test	Not due	08/2019	
Vehicle check	Not due	04/2022	60000

Key Values #15 - BMW of Alexandria , Alexandria

As of Date: April 2, 2018
Odometer Value: 35,447 mi (57,046 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Not due	08/2018	5000
Air filter element	Not due		
Rear brakes	Not due		5000
Vehicle check	Not due	08/2018	5000
Statutory vehicle inspection	Not due	08/2018	
Front Brake	Not due		11000
Brake fluid	Not due	08/2019	
Statutory emissions test	Not due	08/2019	
Fuel filter	Not due		5000
Microfilter	Not due		5000
Re-circulated air filter	Not due		5000

Key Values #16 - Leith BMW Rolls-Royce Motor Cars Raleigh , Raleigh

As of Date: March 30, 2018
Odometer Value: 35,121 mi (56,521 km)

Item Status

Item	Status	Due on	Distance
Rear brakes	Not due		5000
Engine oil	Not due	08/2018	6000
Air filter element	Not due		
Vehicle check	Not due	08/2018	6000
Statutory vehicle inspection	Not due	08/2018	
Front Brake	Not due		11000
Brake fluid	Not due	08/2019	
Statutory emissions test	Not due	08/2019	
Fuel filter	Not due		6000

Microfilter	Not due		6000
Re-circulated air filter	Not due		6000

Key Values #17 - BMW of Alexandria , Alexandria

As of Date: August 25, 2017
Odometer Value: 28,625 mi (46,067 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Overdue	07/2017	-360
Air filter element	Overdue		-360
Statutory vehicle inspection	Overdue	07/2017	
Statutory emissions test	Overdue	07/2017	
Re-circulated air filter	Not due		
Microfilter	Not due		
Fuel filter	Not due		
Brake fluid	Not due	09/2017	
Rear brakes	Not due		9000
Vehicle check	Not due	07/2018	15000
Front Brake	Not due		20000

Key Values #18 - BMW of Mamaroneck

As of Date: July 16, 2016
Odometer Value: 18,975 mi (30,538 km)

Item Status

Item	Status	Due on	Distance
Statutory vehicle inspection	Overdue	09/2015	0
Statutory emissions test	Overdue	09/2015	0
Engine oil	Due soon	08/2016	800
Air filter element	Not due		0
Fuel filter	Not due		0
Brake fluid	Not due	09/2017	0
Rear brakes	Not due		21000
Vehicle check	Not due	08/2018	33000
Front Brake	Not due		34000
Microfilter	Due soon		800
Re-circulated air filter	Due soon		800

Key Values #19 - BMW of Mamaroneck

As of Date: August 6, 2015
Odometer Value: 9,870 mi (15,885 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Overdue	09/2015	-170
Re-circulated air filter	Not due		0
Microfilter	Not due		0
Air filter element	Not due		0
Fuel filter	Not due		0
Statutory vehicle inspection	Not due	09/2015	0
Statutory emissions test	Not due	09/2015	0
Rear brakes	Not due		33000
Brake fluid	Not due	09/2017	0
Front Brake	Not due		43000
Vehicle check	Not due	09/2018	45000

Key Values #20 - BMW of Mamaroneck

As of Date: April 22, 2015
Odometer Value: 7,353 mi (11,833 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Not due	09/2015	4200
Re-circulated air filter	Not due		0
Microfilter	Not due		0
Air filter element	Not due		0
Fuel filter	Not due		0
Statutory vehicle inspection	Not due	09/2015	0
Statutory emissions test	Not due	09/2015	0
Rear brakes	Not due		38000
Front Brake	Not due		46000
Vehicle check	Not due	09/2018	60000
Brake fluid	Not due	09/2017	0

Key Values #21 - BMW of Mamaroneck

As of Date: December 16, 2014
Odometer Value: 3,680 mi (5,923 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Not due	09/2015	11000
Re-circulated air filter	Not due		0
Microfilter	Not due		0
Air filter element	Not due		0
Fuel filter	Not due		0
Statutory vehicle inspection	Not due	09/2015	0
Statutory emissions test	Not due	09/2015	0
Rear brakes	Not due		47000
Front Brake	Not due		50000
Vehicle check	Not due	09/2018	60000
Brake fluid	Not due	09/2017	0

Key Values #22 - BMW of Mamaroneck

As of Date: December 2, 2014
Odometer Value: 3,428 mi (5,517 km)

Item Status

Item	Status	Due on	Distance
Engine oil	Not due	09/2015	11000
Re-circulated air filter	Not due		0
Microfilter	Not due		0
Air filter element	Not due		0
Fuel filter	Not due		0
Statutory vehicle inspection	Not due	09/2015	0
Statutory emissions test	Not due	09/2015	0
Rear brakes	Not due		48000
Front Brake	Not due		50000
Vehicle check	Not due	09/2018	60000
Brake fluid	Not due	09/2017	0

While every reasonable effort is made to ensure the accuracy of this data, we are not responsible for any errors or omissions contained on this page. Please verify any information in question with BMW AG Customer Service or your local BMW dealership. All trademarks and registered trademarks are the property of their respective owners. All trademarks, trade names, service marks, product names, option names and logos are the property of their respective owners.

© 2024 VIN Analytics, LLC. All rights reserved.

